

**RESULT OF SPOT CHECK CARRIED OUT WITH TAXI ENFORCEMENT, POLICE & DVSA  
AT NORFOLK ST GARAGE NELSON, WEDNESDAY 18<sup>th</sup> JULY 2018**

<b>COMPANY</b>	<b>REG AND LICENCE NUMBER</b>	<b>RESULT</b>	<b>ACTION TAKEN</b>
Owner Driver	CV63 DZW HCV 44	Pass	
VIP	FN11 GYW PHV 259	Failed – N/S and O/S Rear Coil spring fractured, N/S windscreen wipers worn.	Licence suspended
Ace/Street Cars	BT11 WNS PHV 250	Failed – Torsion bar fractured, N/S/R Anti roll bar link ball joint snapped, malfunction indicator lamp illuminated indicating a fault, engine MIL and DPF warning lamps illuminated.	Licence suspended
Metro	AF59 WHA PHV 162	Failed – N/S Rear tyre worn beyond limit, O/S side repeater indicator inoperative, N/S rear wheel stud missing, Torsion bar anchorage loose, N/S/F Upper anti roll bar link ball excessively worn, Torsion bar anchorage loose, O/S/F Upper anti roll bar link ball joint excessively worn.	Licence suspended
Tiger - 1 Call Cars	SH11 EXM PHV 157	Failed – Emissions control equipment, obviously defective, evidence DPF been opened, vehicle emitting visible black smoke on acceleration.	Licence suspended
Eagle Star	FT12 XOG– PHV 145	Pass	
Marsden	PX14 UFY HCV 53	Pass	

A - Line	NG63 OXL PHV 81	Pass – Advised loose battery – brake light out.	
HCV – Owner Driver	YA11 OXB HCV 52	Pass	
United	NL60 BUO PHV 390	Failed – N/S/R Tyre seriously underinflated and likely to adversely affect the stability of the vehicle, N/S Outer CV Gaiter split and unable to fulfil its function, N/S/F brake pipe inadequately supported and pipe significantly insecure, brake hose insecure and fouling hub components.	Licence suspended
Alpine	CK11 XCU HCV 58	Failed – O/S/R Tyre beyond legal limit, N/S/F tyres of different size fitted across axle.	Licence suspended
Yellow Cars – O/D	VX15 OFU PHV 415	Passed	
Crown – Hire Car Higher Up	EA67 KVO PHV 599	Pass	
Delta – Hire Car Taxi Assist	FY62 UXO PHV 568	N/S/F Tyre tread worn beyond legal limit.	Licence suspended
Mohammed Shabbir- Owner Driver	DU12 DMF HCV 5	Passed – Advised N/S/F indicator showing white.	

A1	RV57 JVY PHV 217	Failed – O/S/F Door frame broken, door hanging off hinges, window winder broken and unable to close window	Licence suspended
C&E	WA64 ZTM PHV 449	Passed	
Escort	SG62 PZE PHV 430	Failed – Coil spring incorrectly located, O/S/F Coil displaced from upper bearing seat.	Licence suspended
Victors	SJ62 TPZ PHV 430	Failed – Driver admitted to changing O/S/F tyre after being told to bring vehicle into garage for spot check by the Police. Not tested due to repairs carried out.	Licence not suspended due to tyre being changed before inspection.