

**RESULT OF SPOT CHECK CARRIED OUT WITH TAXI ENFORCEMENT, POLICE & VOSA
AT RIGG ST MOTORS, NELSON, 5th JULY 2017**

COMPANY	REG AND LICENCE NUMBER	RESULT	ACTION TAKEN
Four Star & AA Star	DA11 FOP PHV0260	Failed – No fire extinguisher and front side near tyre not fitted correctly.	Licence suspended.
Ace/Street Cars	CA59 RZG PHV0276	Failed – suspension linkage, immediate failure unlikely, offside, anti-roll bar link lower retaining nut loose and excessive movement in steering joint, excessive abnormal movement, nearside, track road end.	Licence suspended
Ace/Street Cars	SJ09 XSV	Failed – excessive movement in steering joint, excessive abnormal movement, nearside, track rod end.	Licence suspended
Matrix Reloaded	SA09 FYL PHV0382	Failed – Non-steered axle tyre tread worn, beyond legal limit, offside rear and CV gaiter split, significantly deteriorated component, nearside outer.	Licence suspended
Cavalier	DA10 ZNY PHV0228	Pass	
Eagle Star	KV60 PZY PHV0188	Pass	
Crown	SN63 FWV PHV 0179	Pass	

Crown	WF09 HOA HCV0059	Failed - direction indicator inoperative, and cannot be used to clearly show the drivers intention, offside, side repeater lamp.	Licence not suspended due to a new bulb immediately fitted at the garage.
Union	AM58 CWG PHV0317	Failed – (1) steered axle tyre tread worn, beyond legal limit, nearside front; excessive movement in steering joint, excessive abnormal movement, steering column universal joint, (2) suspension arm, immediate failure unlikely, offside front, bottom ball joint excessively worn, (3) suspension arm, immediate failure unlikely, nearside front, bottom ball joint excessively worn, (4) non-steered axle tyre tread worn, beyond legal limit, offside rear.	Licence suspended.
Victors	TN07 SDX PHV0238	Passed	
VIP – hire car	KU14 CMY PHV0530	Passed	
NCB	NX06 VTF	Failed – (1) CV Gaiter split, split and unable to fulfil its function, nearside inner, (2) Obligatory seat belt, not fitted where legally required, nearside rear seat belt latch missing.	2 day delayed suspension notice issued.
HCV OWNER/DRIVER	YY11 VKK HCV0039	Passed	
ALINE/LOCAL	FD10 CFX PHV0093	Passed – defect notice issued for a rear brake light out.	Defect notice issued.

