

**RESULT OF SPOT CHECK CARRIED OUT WITH TAXI ENFORCEMENT, LANCASHIRE CONSTABULARY AND VOSA  
AT JOHN MACADAM & SON (GARAGES) LIMITED ON 21 MARCH 2014**

<b>COMPANY</b>	<b>REG OF VEHICLE</b>	<b>RESULT</b>	<b>ACTION TAKEN</b>
Eagle Star	OE55 LHM	Passed vehicle inspection	
A-Line – Gemms	WR07 CXN	Passed vehicle inspection	
Escort	KM06 KTN	Passed vehicle inspection	
Alpine – HC 58	FV57 EPL	Passed vehicle inspection	
C&E	E056 NHL	N/S Gaiter split, split and unable to fulfil its function	Delayed prohibition issued, licence suspended – repaired and suspension lifted on 24/3/2014
Owner Driver – HC 22	KU07 HND	New first aid kit and fire extinguisher needed – passed vehicle inspection	
C&E	SJ57 YHP	Brake adjustment indicator shows that brake adjustment is necessary, braking system requires attention, no reserve travel handbrake	Delayed prohibition issued, licence suspended – repaired and suspension lifted on 24/3/2014
Owner driver – HC 29	MH54 NAS	Number plates to be replaced – passed	
Kings	LM05 UHE	O/S front tyre beyond legal limit, N/S front tyre beyond legal limit	Immediate prohibition issued, licence suspended – repaired and suspension lifted on 27/3/2014
Owner driver – HC7	FE57 HJJ	Passed vehicle inspection	
Union	LR53 VSF	Passed vehicle inspection	
Union	YF55 XGN	Nearside headlamp inoperative, oil leak from engine causing patch in excess of 75mm in five minutes	Immediate prohibition issued, licence suspended – repaired and suspension lifted on 24/3/2014
BCN	FH08 YFX	Passed vehicle inspection	