

**RESULT OF SPOT CHECK CARRIED OUT WITH TAXI ENFORCEMENT AND VOSA
AT NORFOLK ST GARAGE, NELSON, 10th NOVEMBER 2017**

COMPANY	REG AND LICENCE NUMBER	RESULT	ACTION TAKEN
Ace/Street Cars	HN11 CXW PHV 272	Failed – O/S CV Gaiter split and unable to fulfil its function, malfunction indicator lamp illuminated indicating a fault, emission dash warning lamp on at all times.	Licence suspended
United	DG11 KSY PHV 404	Pass	
Matrix Reloaded	AD10 RWN PHV 79	Pass	
Alpine	BD07 OJV PHV 291	O/S Sliding door jammed	Licence suspended
HCV OWNER/DRIVER	LV58 COJ HCV 11	Pass	
VIP	SL11 EPJ PHV 123	Pass	
C&E	FH07 RZW PHV 160	Pass	
Union	AE58 TRV PHV 317	Exhaust system leaking, fumes likely to enter vehicle, battery insecure displacement constitutes risk of fire, N/S wheel stud missing.	Licence suspended

Crown and Greenline	VU58 KYX PHV 178	Failed – O/S wheel stud missing.	Licence suspended
Eagle Star	KU60 PZY PHV 188	Passed	
Pendle Taxi	LS11 OKJ PHV 532	Failed – N/S CV Gaiter split, split and unable to fulfil its function	Licence suspended
Pendle Taxi	HY11 XNE PHV 397	Failed – No fire extinguisher or first aid kit, N/S headlamp inoperative, N/S CV gaiter split and unable to fulfil its function.	Licence suspended
A-Line	AV62 FBE PHV 262	Pass	