## RESULT OF SPOT CHECK CARRIED OUT WITH TAXI ENFORCEMENT, POLICE & VOSA AT NORFOLK STREET GARAGE ON 1st NOVEMBER 2013

COMPANY	REG OF VEHICLE	RESULT	ACTION TAKEN
Ace	WV56 PYB	Passed vehicle inspection	5 day defect notice issued due to N/S rear light cracked.
Crown & Greenline	FL06 CXD	Headlamp inoperative and use of headlamp Compulsory, offside.	Licence suspended – repaired and plate returned same night - suspension lifted as from that date.
BCN/ Adams.	FH08 YFX	N/S front tyre tread worn beyond legal limit, O/S rear coil spring fractured.	Licence suspended – repaired and plate returned 02/11/13 - suspension lifted as from that date.
Matrix	BV56 ONO	Passed vehicle inspection	First aid kit and fire extinguisher missing from vehicle, replaced same night.
4 Star	MV59 LLF	Passed vehicle inspection	
Owner Driver HC15	AV57 YTC	Passed vehicle inspection	
Pennine	YJ07 MOT	N/S front tyre has deep cut, body cords exposed, airbag light on – MOT failure.	Licence suspended – repaired and plate returned same night - suspension lifted as from that date.
Superline	VA54 NVH	Excessive fluid leak from power steering, N/S inner CV Gaiter and unable to fulfil its function, N/S outer front CV Gaiter insecure, significantly deteriorated component.	Licence suspended – repaired and plate returned 02/11/13 - suspension lifted as from that date
VIP	HY06 HLN	N/S front tyre tread worn, beyond legal limit.	Licence suspended – repaired and plate returned 02/11/13 - suspension lifted as from that date

		I	1
Higher Up – Hired out to Cavalier	FV61 CHH	Airbag light on – MOT failure, front bumper grill missing.	Licence suspended – repaired and plate returned on same night - suspension lifted as from that date
Hackney Carriage – owner/driver HC23	DE55 XOS	Passed vehicle inspection	
Hackney Carriage – owner/driver HC62	YF55 RZT	N/S rear coil spring fractured, rear tyres of different nominal size.	Licence suspended – repaired and plate returned 02/11/13 - suspension lifted as from that date
Cavalier	VK05 WWZ	Passed vehicle inspection	
Higher Up – Hired out to Victors	DN12 MUP	O/S front tyre tread worn, beyond legal limit.	Licence suspended – repaired and plate returned on same night - suspension lifted as from that date
A1 Speedline	RV57 JVY	N/S and O/S front tyres beyond legal limit.	Licence suspended – repaired and plate returned 02/11/13- suspension lifted as from that date