

**RESULT OF SPOT CHECK CARRIED OUT WITH TAXI ENFORCEMENT, POLICE & VOSA
AT RIGG STREET GARAGE ON 06th April 2016**

COMPANY	REG OF VEHICLE	RESULT	ACTION TAKEN BY VOSA & COUNCIL
C&E	SJ57 YHP – Licence 205	Passed vehicle inspection	Advisory items from VOSA - Lights
Crown & Greenline	FH07 TVD – Licence 3	O/S Tyre beyond legal limit, battery insecure, O/S rear bush excessively worn, O/S brake pad excessively worn, braking system component malfunctioning.	Immediate Prohibition - Licence suspended – repaired and plate returned on 08/04/16
Eagle Star	MV57 NDD – Licence 87	N/S tyre tread bulging, front wheel drive shaft excessively worn, braking system component malfunctioning, excessive movement in steering joint excessive abnormal movement, CV Gaiter insecure significantly deteriorated.	Immediate Prohibition - Licence suspended – Vehicle replaced.
Liaquat Ali -HCV19	PE58 SWY- Licence 19	Passed vehicle inspection	Advisory item from VOSA – Brake pads getting low
Metro	GV58 KYC - Licence 222	Passed vehicle inspection	Advisory item – Tyre getting to limit.
Yellow Cars	VN08 MHU- Licence 359	Tyre Bulging – excessive movement in steering joint, excessive abnormal movement lower suspension ball joint – shock absorber leaking.	Immediate prohibition - Licence suspended – repaired and plate returned on 07/04/16
Tiger and 1 Call	FL58 DMU- Licence 245	Brake pads excessively worn – Advisory items – Oil leak from engine – Axle bushes excessively worn N/S and O/S.	Delayed Prohibition -Licence suspended repaired and plate returned same day

Union	DY58 DNN – Licence 337	Direction indicator inoperative cannot be used to show drivers intention O/S side repeater – wheel stud missing – N/S Brake pads excessively worn	Immediate Prohibition - Licence suspended – repaired and plate returned 08/04/16
VIP	PY58 AHL – Licence 176	N/S front tyre tread worn, beyond legal limit, N/S coil spring fractured, Anti lock brake warning light indicates a fault, O/S CV Gaiter split significantly deteriorated.	Immediate Prohibition - Licence suspended – repaired and plate returned 07/04/16
A-Line	SM08 SVU – Licence 319	N/S Tyre tread worn beyond legal limit, O/S and N/S direction indicator inoperative, excessive movement in steering joint, excessive abnormal movement, O/S lower ball joint, CV Gaiter insecure significantly deteriorated.	Immediate Prohibition - Licence suspended – repaired and plate returned on 10/04/16
Matrix	SG08 KNS – Licence 344	O/S front and O/S rear doors deliberately secured cannot be opened from inside or outside.	Immediate Prohibition - Licence suspended – repaired and plate returned on 07/04/16
Taxi Assist	PE61 UML – Licence 507	Direction indicator inoperative and cannot be used to clearly show drivers intention, O/S side repeater.	Immediate Prohibition - Licence suspended – repaired and plate returned on same day
M Ilyas – HCV 46	SB58 HHB – Licence 46	N/S Brake hose bulging, risk of further damage, O/S front direction indicator insecure detachment imminent.	Immediate Prohibition - Licence suspended – repaired and plate returned on 07/04/16
Shabaz Ahmed Yellow Cars	NL08 BLK – Licence 110	Passed vehicle inspection.	
Ace	DA58 ZBY – Licence 207	N/S Steering arm insecure detachment imminent, track rod end insecure on steering rack, suspension sub frame bolts loose.	Immediate Prohibition - Licence suspended – repaired and plate returned 09/04/16

