RESULT OF SPOT CHECK CARRIED OUT WITH TAXI ENFORCEMENT, POLICE & VOSA AT NORFOLK ST GARAGE, NELSON, TUESDAY 20th MARCH 2018

COMPANY	REG AND LICENCE NUMBER	RESULT	ACTION TAKEN
Metro	FV61 CMX – PHV 246	Failed – O/S Indicator inoperative, N/S/R seat belt stalk serious deterioration, buckle shroud damaged, N/S/F suspension linkage anti roll bar link ball joint gaiter holed and ineffective.	Licence suspended
Pendle – Owner Driver	NJ60 YJE – PHV 136	Failed - No first aid kit, no fire extinguisher, boot trim damaged, opening not working.	Licence suspended
A - Line	BJ59 EHV – PHV 156	Defect notice issued - oil leak, N/S/F side light out	Defect notice issued
Street Cars/Ace	BT11 WNS – PHV 250	Defect notice issued – reverse light inoperative, engine management light on, oil leak.	Defect notice issued
HCV	PK58 DXC – HCV 61	Passed	
Crown	OY62 PJV – HCV 31	Passed	
Pendle – Owner Driver	VA12 FOM – PHV 417	Passed	
Street Cars/Ace	FY09 YDL – PHV 298	Failed – N/S/R Tyre has deep cut in tread area, breaker cords damaged.	Licence suspended

		1	
Union	FE63 KBY – PHV 423	Failed – N/S row 2 seat belt webbing has serious deterioration, seatbelt unusable as buckle impeded, N/S/R brake hose kinked, incorrectly fitted causing kinks at both hose unions.	Licence suspended
Tiger/1 Call	SH11 EXM – PHV 157	Failed – N/S track rod end excessive movement in steering joint, suspension arm N/S front anti roll bar link lower ball joint gaiter deteriorated.	Licence suspended
Cavalier	FL60 TBU – PHV 402	Passed	
VIP	YO15 VHU – PHV 418	Failed – SRS Mil illuminated, SRS Mil indicates any kind of failure of the system, dashboard warning light continuously illuminated.	Licence suspended
HCV	WV12 DYB – HCV 16	Failed – N/S outer CV Gaiter split and significantly deteriorated, O/S front forward bush excessively worn, O/S front indicator inoperative.	Licence suspended
Union	DY58 DNN – PHV 337	Failed - N/S/F Outer CV Gaiter split and unable to fulfil its function.	Licence suspended
Street Cars/Ace	SJ09 XSV – PHV 315	Failed – N/S/R Tyre beyond legal limit.	Licence suspended
Delta	FR13 SVG – PHV 509	Passed	