Pendle Strategic Housing Land Availability Assessment

| Site Details | | | | | | | |
|---|--|--|------------------|-------------------------------------|-------------------------------------|-----------------------|--|
| Site Ref: S196 Site Na | ame: St. Michael's Vicarage, Skipton F | | | Road Settlement: | | Foulridge | |
| Postcode Sector: BB8 7 W | Vard: Foulrid | ge Ward | Plann | ing App: N/A | SHLAA Typology | : I (Garden Land) | |
| Site Area (gross): 0.44ha Ir | ndicative No. D | Owellings: | 9 India | ative Density: | 20 dph Co-ordinates | : 389026, 441974 | |
| Suitability – location and infrastructure | | | | | | | |
| (S0) Within a Settlement Boun | idary? Yes | | | (S1) Brownfield / G | Greenfield? | Brownfield | |
| (S2) Car parking? | Yes | | | (S3) Loss of employ | yment land? | No | |
| (S4) Protected employment are | ea? No | | | (S5) Open space / | settlement character? | No No | |
| (S7) Suitable infrastructure? | Partial | | | (S8) Infrastructure | capacity? | Yes | |
| (\$7/\$8) Infrastructure commer | | | _ | | eed extending but sho | | |
| Suitability – environment and heritage | | | | | | | |
| (S9) Contamination? | None identifi | ed | | (S10) Topography: | Flat | | |
| (S11) Flooding issues / Flood zone: | Not within ar site. | n identified | Flood Zone. | No other flooding is | ssues identified on- | Flood Zone 1 | |
| (S28) Conservation Area: | No | | 1.70 km | (S29) Listed Buildir | ng: No | 0.31 km | |
| (S30) Scheduled Monument: | No | | | (S31) Archaeology: | | | |
| (S32) TPO: | Yes | | | (S37) Poor air qual | | | |
| (S33) Ecology: | Potential fror designated si | • | y to a | (S34) Nature Conso | ervation Site within 25 designation | 50m of a 0.09 km | |
| (S33/S34) Natural | | | signated natu | | es on this site. The site | e is within 250m of a | |
| designated nature conservation site. The site is not covered by an area of ecological interest (least record). In terms of agricultural classification the site is classed as Grade 4 - poor quality farmland. | | | | | | ogical interest (LERN | |
| (S35/S36) Bad neighbour uses | No bad neigh | bouring us | es - this site i | s surrounded by ex | isting residential prope | erties. New | |
| and impact on surround area: development unlikely to have an adverse impact on the surrounding uses. | | | | | | | |
| (S39) Coal Mining: No (S40) Mineral Safeguarding Area (MSA): No | | | | | | | |
| Suitability – distance to services (km) | | | | | | | |
| (S12) Railway station: | 3.10 | (S13) Bus st | top: | 0.13 | (S13a) Bus stop frequ | uency: >15 mins | |
| (S14) Primary school: | 0.48 | (S15) Secor | ndary school: | 1.80 | (S16) Sports/leisure | centre: 3.10 | |
| (S17) Doctors: | 2.00 (| (S18) Hospi | ital: | 5.80 | (S19) Town / Local ce | entre: 1.90 | |
| (S20) Supermarket/store: | 1.63 (| 1.63 (S21) Employment area: 1.90 (S22) | | | (S22) Public house: | 0.17 | |
| (S23) Corner shop: | 1.60 (| (S24) Post (| Office: | 1.80 | (S25) Open space: | 0.16 | |
| (S26) PROW: | 0.03 | (S27) Cycle | route: | 0.46 | | | |
| Availability | | | | | | | |
| (A1) Access issues? No (A2) \ | | | | (A2) Vehicular acce | 2) Vehicular access: Good | | |
| (A3) Visibility splays / highway | /s issues? Ad | equate | | (A4) In use? | Partial | | |
| (A5) Ownership? 1 owner - Private | | | | | | | |
| Achievability | | | | | | | |
| (V1) Competing land use? No | | | | (V2) Market Attractiveness? High | | | |
| (V3) Viable? Viable | | | | (V3) Viability Model Ref: Scheme 12 | | | |
| This site is located within the village of Foulridge. The site is not covered by any specific policy designation. The Council's viability model indicates that this type of site is viable to develop. The land owner is willing to develop the site and has completed the site survey form indicating that financial viability is not a constraint to development. A planning application was refused on the site on highways grounds, however, alternative access arrangements can be made and if a new planning application is approved the site could come forward in five years. | | | | | | | |
| Constraints: No constraints | identified. | | | | | | |
| Timescales (No. dwellings) | | | | | | | |
| | | ear Period | | | 6-10 Years | 11-15 Years | |
| 2014/15 2015/1 | .6 20 | 16/17 | 2017/1 | | | 2024-29 | |
| 0 0 | | 4 | 5 | 0 | 0 | 0 | |

Pendle Strategic Housing Land Availability Assessment

Site Name: St Michael's Vicarage, Skipton Road

Location: Foulridge Site Ref: S196

Site Area: 0.43 ha **Grid Ref:** SD 389 441









