

IMPROVEMENTS TO WYCOLLER FOOTPATH

Works carried out by C. Braithwaite
July 2015







Work in progress































A photograph of a stream with a displaced gabion basket and a bridge in the background. The stream is dark and calm, reflecting the surrounding greenery. A large, rectangular gabion basket, made of wire mesh and filled with rocks, is partially submerged in the water. The basket is tilted and appears to have been moved from its original position. The surrounding area is lush with green grass and various plants, including some yellow wildflowers. In the background, a metal truss bridge spans the stream, supported by concrete piers. The scene is set in a wooded area with trees and bushes visible along the banks.

Displaced gabion basket removed by hand

























Area partially filled first to allow site traffic







Filled depression with pipe under

























END