

REPORT FROM:PLANNING, BUILDING CONTROL AND LICENSING SERVICES MANAGERTO:BARROWFORD AND WESTERN PARISHES COMMITTEEDATE:6<sup>th</sup> JULY 2017

## **PROBLEM SITES**

		Key History	CURRENT POSITION	ACTION BY
Former Corn Mill, Gisburn Road, Barrowford	Condition of building.		Meeting held and discussions progressing with owner. The Community Protection Co- ordinator provided an update report at the last meeting. The caravan has been removed from the site. Any further progress will be reported at the meeting.	TH
Spen Brook Mill, Spenbrook Road, Spenbrook	Condition of the site.		Work has been completed on the partial demolition of the mill. It is informally understood that development will go ahead on the site.	Planning
	Mill, Gisburn Road, Barrowford Spen Brook Mill, Spenbrook Road,	Mill, Gisburn   Road,   Barrowford   Spen Brook   Mill,   Spenbrook   Road,	Mill, Gisburn   Road,   Barrowford   Spen Brook   Mill,   Spenbrook   Road,	Mill, Gisburn Road, Barrowfordwith owner. The Community Protection Co- ordinator provided an update report at the last meeting. The caravan has been removed from the site. Any further progress will be reported at the meeting.Spen Brook Mill, Spenbrook Road,Condition of the site.Work has been completed on the partial demolition of the mill. It is informally understood that development will go ahead on the site.