

REPORT FROM: PLANNING, BUILDING CONTROL AND LICENSING SERVICES MANAGER

TO: BARROWFORD AND WESTERN PARISHES COMMITTEE

DATE: 9th NOVEMBER 2017

## **PROBLEM SITES**

SITE	ISSUE	Key History	CURRENT POSITION	ACTION BY
Former Corn Mill, Gisburn Road, Barrowford	Condition of building.		Meeting held and discussions progressing with owner. The Community Protection Coordinator provided an update report at the last meeting. The caravan has been removed from the site. Any further progress will be reported at the meeting.	TH
Spen Brook Mill, Spenbrook Road, Spenbrook	Condition of the site.		Work has been completed on the partial demolition of the mill. It is informally understood that development will go ahead on the site.	Planning
	Former Corn Mill, Gisburn Road, Barrowford  Spen Brook Mill, Spenbrook Road,	Former Corn Mill, Gisburn Road, Barrowford  Spen Brook Mill, Spenbrook Road,	Former Corn Mill, Gisburn Road, Barrowford  Spen Brook Mill, Spenbrook Road,	Former Corn Mill, Gisburn Road, Barrowford  Spen Brook Mill, Spenbrook Road, Road, Meeting held and discussions progressing with owner. The Community Protection Coordinator provided an update report at the last meeting. The caravan has been removed from the site. Any further progress will be reported at the meeting.  Work has been completed on the partial demolition of the mill. It is informally understood that development will go ahead on the site.