

REPORT FROM:PLANNING, ECONOMIC DEVELOPMENT AND REGULATORY SERVICES MANAGERTO:BARROWFORD AND WESTERN PARISHES COMMITTEEDATE:4th JULY 2019

PROBLEM SITES

REF	SITE	ISSUE	Key History	CURRENT POSITION	ACTION BY
1	Spen Brook Mill, Spenbrook Road, Spenbrook	Condition of the site.		 Work has been completed on the partial demolition of the mill. An application for an additional house is pending consideration. Discussions relating to outstanding conditions on-going with agent. The fencing to the site has been addressed and development is expected to re-commence shortly. Continue to monitor. 	КН