RESULT OF SPOT CHECK CARRIED OUT AT NORFOLK ST GARAGE, NELSON, 10th NOVEMBER 2023

RESULT	ACTION TAKEN
5 vehicles passed the test	No action
Failed - N/S/R, wheel nut missing.	Vehicle taken off road – revert to 4 monthly testing
Failed – N/S/F anti roll bar link lower ball joint excessively worn, N/S/F side light inoperative	Vehicle taken off road – revert to 4 monthly testing
Failed – O/S/R spring broken.	Vehicle taken off road – revert to 4 monthly testing
Failed – N/S/F tyre blow legal limit, O/S/F link excessive play	Vehicle taken off road – revert to 4 monthly testing
Failed – O/S/R shocker leaking, front brake pads below limit.	Vehicle taken off road – revert to 4 monthly testing
Failed – N/S/R tyre below legal limit	Vehicle taken off road – revert to 4 monthly testing
Failed – N/S/F CV boot insecure, excessive oil leak	Vehicle taken off road – revert to 4 monthly testing
Failed – Hand brake inoperative, O/S/F wheel nut missing, airbag light on	Vehicle taken off road – revert to 4 monthly testing
Failed – O/S/F link excessive play	Vehicle taken off road – revert to 4 monthly testing
Failed – O/S/F shocker leaking, tyre pressure monitoring light on	Vehicle taken off road – revert to 4 monthly testing
Failed – O/S/F track rod end excessive play, O/S/R tyre below legal limit	Vehicle taken off road – revert to 4 monthly testing

RESULT OF SPOT CHECK CARRIED OUT WITH TAXI ENFORCEMENT, DVSA & POLICE AT NORFOLK ST GARAGE, NELSON, 18th JANUARY 2024

RESULT	ACTION TAKEN
10 vehicles passed the check	No action
Failed - CV Gaiter insecure, significantly deteriorated component, O/S/F detached from joint. Rear centre belt latch incorrect and seatbelt cannot be used.	Vehicle taken off road – revert to 4 monthly testing
Real Centre Deit laten incorrect and seatbeit cannot be used.	
Failed – N/S/F Tyre beyond legal limit	Vehicle taken off road – revert to 4 monthly testing
Failed – N/S Outer CV gaiter split and unable to fulfil its function.	Vehicle taken off road – revert to 4 monthly testing
Failed – O/S side repeater indicator inoperative	Vehicle taken off road – revert to 4 monthly testing
Failed – O/S side repeater indicator inoperative, Fluid leaking from engine causing a patch in excess of 75mm diameter in 5 minutes.	Vehicle taken off road – revert to 4 monthly testing
Failed – O/S/F tyre beyond legal limit, flat spots.	Vehicle taken off road – revert to 4 monthly testing
Failed – DPF (diesel particulate filter) Tampered	Vehicle taken off road – revert to 4 monthly testing
Failed – Engine management light on. O/S/F wing mirror glass broken	Vehicle taken off road – revert to 4 monthly testing
Failed – Door jammed, O/S/R outer door handle broken, door cannot be opened from outside the vehicle.	Vehicle taken off road – revert to 4 monthly testing
Failed – Tyres of different size fitted, fitted across an axle, N/S axle 2 has a space saver fitted.	Vehicle taken off road – revert to 4 monthly testing